



NOTE: DUE TO EXTENSIVE WATER SEEPAGE BETWEEN ROOF GUTTER AND WALL AT ROOF'S EDGE THERE ARE QUITE A FEW VISIBLE SOFT/ROTTEN AREAS ON THESE UPPER WINDOWS. NOTIFY ARCHITECT OF ANY INTERIOR DAMAGE TO WOOD BLOCKING THAT MAY APPEAR DURING CONSTRUCTION.

NOTE: DETAILED SECTIONS REPLICATED FROM ORIGINAL CONSTRUCTION DOCUMENTS



Office of the State
Public Defender
District 8 Office
Building

111 West Main Street
Winnfield, LA 71483

CDMorgan
& ASSOCIATES, INC.
ENGINEERING CONSULTANTS
A PROFESSIONAL ENGINEERING AND ARCHITECTURAL CORPORATION
LOUISIANA
(337) 886-1280
www.CDMorgan.com



Seal:

No.	Description	Date